

Initial HS&E Incident & Accident Notification

Location: (Section and exact location)	South Section, PS08
Section Director:	David Hill
Incident Type:	<input type="checkbox"/> Loss/Damage/Theft <input type="checkbox"/> Near Miss/Close Call (Specify type) <input type="checkbox"/> Injury <input type="checkbox"/> Illness <input type="checkbox"/> Utility Damage <input type="checkbox"/> Environmental <input type="checkbox"/> Road Traffic Accident/Incident <input type="checkbox"/> Overturn Plant
Date & Time of Incident:	11/04/17
Date & Time Incident Reported:	11/04/17

Brief Description of the Incident

Merlo 360 Degree tele-handler lifting appliance has been positioned adjacent to the PS08 structure at a lower level, wheels only- i.e. no outriggers deployed, the operator had a tipping skip on the forks and had boomed out and up to allow operatives on the structure deck to hand-ball load materials into the skip. As the operator retracted the loaded skip the machine has begun to tip over to the boom side and has overturned ending up on its side. The fork attachment and the skip has detached from the appliance. The operator states that he is uninjured having braced himself during the overturning. Investigation has commenced, operator has been D&A tested with a negative result, statements are currently being taken and we are awaiting the plant owner, Greenwoods, attending site to discuss method of recovery. (Machine & operator supplied by Greenwoods)

Photographs/Sketches



Additional photos below

Immediate Actions / Current Status

The appliance was segregated and secured.
Incident notification process commenced immediately, Operator assessed for injury, D&A Testing arranged.
08.30 Safety Manager & Advisor on site to commence investigation, which is ongoing at present.

